

Wył. Szybki					Tabela załączeń stycznych wału SK																			
Poł.		WS1	WS2	WS3	WS4	SK1	SK2	SK3	SK4	SK5	SK6	SK7	SK8	SK9	SK10	SK11	SK12	SK13	SK14	SK15	SK16	SR1-2	SM1-2	SL1-2
Szerogowa	1	●	●	●	●							●	●							●	●		●	●
	2	●	●	●	●	●						●	●										●	●
	3	●	●	●	●	●	●					●	●										●	●
	4	●	●	●	●	●	●	●				●	●										●	●
	5	●	●	●	●		●	●	●			●	●										●	●
	6	●	●	●	●			●	●	●		●	●										●	●
	7	●	●	●	●				●	●	●	●	●										●	●
	8	●	●	●	●					●	●	●	●	●									●	●
	9	●	●	●	●						●		●	●	●								●	●
P	10	●	●	●	●									●	●								●	●
Równoleg.	11	●	●	●	●									●	●							●	●	●
	12	●	●	●	●	●	●							●	●							●		●
	13	●	●	●	●	●	●	●	●					●	●							●		●
	14	●	●	●	●			●	●	●	●			●	●							●		●
	15	●	●	●	●					●	●	●	●	●	●							●		●
Bocz.	16	●	●	●	●							●	●			●	●					●		●
	17	●	●	●	●							●	●			●	●	●	●			●		●
	18	●	●	●	●							●	●					●	●	●	●	●		●